



REPUBLIC
SERVICES

28470 Citrin Drive Romulus, MI 48174
o 734.946.1000 republicservices.com

March 30, 2020

Mr. Allan Batka
United States Environmental Protection Agency
Region 5 (WU-16J)
77 West Jackson Blvd.
Chicago, Illinois 60604

Re: RIES Monthly Report (in conformance with MI-163-1W-C010 & MI-163-1W-C011)

Dear Mr. Batka:

Republic Industrial and Energy Solutions, LLC. ["RIES", formerly Environmental Geo-Technologies, LLC ("EGT")] hereby timely submits its seventy-sixth Monthly Report ("MR") in conformance with the requirements of its two EPA UIC permits (#s MI-163-1W-C010 & MI-163-1W-C011).

RIES is providing all of the attached information in the same sequence as required by both subject permits, i.e. Part II.D.1 (a-i), Part III, Attachment A, and Part III, Attachment E.G.2 & E.I. As for the last few months, there are a few computerized sheets absent from this report because the computer systems continue to be upgraded, and once completed, I will forward them (for September, October, November, December 2019, January and February 2020 summary sheets) on to you. RIES did not accept any F039 waste in February, 2020 so no Page A-3 of 3 laboratory analyses are necessary to be submitted as part of this MR.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

We trust that you find this report satisfactory, however, if you have any questions or comments, please feel free to contact us.

Sincerely,

Richard J. Powals, P.E.

cc: J. Frost (RIES)

att.

rjp033020/RIESEPA Monthly Report-February, 2020

AVERAGE INJECTION RATE

Calculation of Average Injection Rate

CURRENT REPORTING YEAR 2020

CURRENT REPORTING MONTH FEBRUARY

Date (month, year) of the first injection into either well at the Citrin Road Facility
NOV 2013

CURRENT MONTH (all volumes in gallons)

	Injected Waste	Injected Non-Waste	Total injected
MI-163-1W-C010, Well #1-12			
Current Month	0	0	0
Since facility first injected			14,567,965
MI-163-1W-C011, Well #2-12			
Current Month	0	0	0
Since facility first injected			4,648,763
		Lifetime Combined	19,216,701

Conversion factors

365.25 days per year ÷ 12 months per year = 30.4375 days per month

30.4375 days per month × 1440 minutes per day = 43,830 minutes per month

Calculations

Whole number of months of injection 74

$$\text{_____ lifetime number of months of injection} \times 43,830 \text{ minutes/month} = \underline{3,243,420} \text{ minutes of injection}$$

$$\text{Lifetime combined injected volume } \underline{19,216,701} \div \underline{3,243,420} \text{ minutes of injection} = \underline{5.9} \text{ gpm average injection rate}$$

WELL 1 DATA

Circle Chart Index

Environmental Geo-Technologies, LLC 28470 Citrin Drive Romulus, MI 48174

Chart Recorder #1

Channel #1

Blue Pen - Well 1 Injection Pressure (chart value x 30)

Channel #2

Red Pen - Well 1 Annulus Pressure (chart value x 30)

Channel #3

Green Pen - Well 1 Flow Rate (chart value x 4)

Channel #4

Black Pen - Well 1 Annulus Tank Level (chart value x 0)

Chart Recorder #2

Channel #1

Blue Pen - Well 2 Injection Pressure (chart value x 30)

Channel #2

Red Pen - Well 2 Annulus Pressure (chart value x 30)

Channel #3

Green Pen - Well 2 Flow Rate (chart value x 4)

Channel #4

Black Pen - Well 2 Annulus Tank Level (chart value x 0)

Chart Recorder #3

Channel #1

Blue Pen - Injection pH Well 1 & 2 (chart value = 3.3)

Channel #2

Red Pen - Well 1 Monthly Volume (chart value x 100,000)

Channel #3


Green Pen - Well 2 Monthly Volume (chart value x 100,000)

Channel #4

Black Pen - Temperature (chart value x 0)

DATA DESCRIPTION


In the month of February no waste was received, and no injection was performed. There is no tabulated data in this report because the SCADA operating system continues to be upgraded and rebuilt. The tabulated data is still being recorded in the old hard drive but needs to be specifically retrieved by the programmer.



DATE
2-6-20
NO.
1
CHART NO. GDSV0850UD50


THURSDAY
NOON
9
A.M.

WEDNESDAY
NOON
9
A.M.



DATE CR-1 NO. 2/13
CHART NO. GDSV0050U030

THURSDAY 3 P.M. 9 AM
FRIDAY NOON 3 P.M. 9 AM
SATURDAY NOON 3 P.M. 9 AM
SUNDAY NOON 3 P.M. 9 AM



DATE 2/20/2010 NO. R-1
CHART NO. GDSV0050UD50


AM 9

NOON

PM

THURSDAY NOON

WEDNESDAY NOON



DATE 2-27-20 NO. CE-1

CHART NO. GDSV0050U050

THURSDAY

WEDNESDAY

9 AM

3 PM

WELL 2 DATA

Circle Chart Index

Environmental Geo-Technologies, LLC 28470 Citrin Drive-Romulus, MI 48174

Chart Recorder #1

Channel #1

Blue Pen - Well 1 Injection Pressure (chart value x 30)

Channel #2

Red Pen - Well 1 Annulus Pressure (chart value x 30)

Channel #3

Green Pen - Well 1 Flow Rate (chart value x 4)

Channel #4

Black Pen - Well 1 Annulus Tank Level (chart value x 0)

Chart Recorder #2

Channel #1

Blue Pen - Well 2 Injection Pressure (chart value x 30)

Channel #2

Red Pen - Well 2 Annulus Pressure (chart value x 30)

Channel #3

Green Pen - Well 2 Flow Rate (chart value x 4)

Channel #4

Black Pen - Well 2 Annulus Tank Level (chart value x 0)

Chart Recorder #3

Channel #1

Blue Pen - Injection pH Well 1 & 2 (chart value ± 3.3)

Channel #2


Red Pen - Well 1 Monthly Volume (chart value x 100,000)

Channel #3

Green Pen - Well 2 Monthly Volume (chart value x 100,000)

Channel #4

Black Pen - Temperature (chart value x 0)



DATE

NO.

7-6-20

2

CHART NO. 686490501050

0

10

20

30

40

50

40

30

20

10

0

30

20

10

0

30

20

10

0

40

30

20

10

0

10

20

30

40

30

40

50

3 PM

NOON

WEDNESDAY

9 AM

THURSDAY

NOON

3 PM

9 AM

NOON

FRIDAY

9 AM

50

40

30

20

10

0

10

20

30

40

50

30

20

10

0

3 PM

NOON

WEDNESDAY

FRIDAY

NOON

9 AM

40

30

20

10

0

30

20

10

0

30

20

10

0

40

30

20

10

0

10

20

30

40

30

20

10

0

3 PM

NOON

WEDNESDAY

FRIDAY

NOON

9 AM

40

30

20

10

0

30

20

10

0

30

20

10

0

40

30

20

10

0

10

20

30

40

30

20

10

0

3 PM


NOON

WEDNESDAY

FRIDAY

NOON


9 AM



DATE 2/13

NO. CR-2

CHART NO. GDSV0050U050



DATE 2/20/2020 NO. CL-2
CHART NO. GDSV0050U050

9 AM

50

3 PM

THURSDAY

NOON

9

AM

50

3 PM

WEDNESDAY

NOON

9

5 AM

30

40

40

50

3 PM

50

40

30

20

10

10

20

30

40

10

20

30

40

50

20

30

40

50

30

40

50

3 PM

40

50

5 AM

40

30

20

10

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30

40

50

60

70

80

90

0

10

20

30


40

50

60

70

PRINTED IN U.S.A.
SUNDAY
NOON





DATE
2-27-20

No.

02-2

CHART NO. GDSV0050US0






DATE
2/13

NO.
CR-3

CHART NO. GDSV0050U050




DATE
2/13

NO.
CR-3

CHART NO. GDSV0050U050

PRINTED IN U.S.A.
SUNDAY
NOON



DATE 2/20/2020
NO. CR-3
CHART NO. GDSV00501050

FRIDAY
NOON

SATURDAY
NOON


THURSDAY
NOON

P.M.

A.M.

P.M.

A.M.



DATE
2-27-20

NO.
CR-3

CHART NO. GDSV10050U050

CORROSION MONITORING

COOROSION MONITORING COUPONS VISUAL DESCRIPTION

Feb, 2020

Fiberglass Coupon

The coupon is dark orange (rust) in color with a semi-smooth texture on both sides. Its cut edges appear sanded. The coupon is free of cracks, pitting, swelling, blemishes, and corrosion. There is no obvious effect on this coupon since last month.

Hastelloy Coupon

This coupon is identified as C276 with Serial Number 5. The coupon is silver in color with a lightly sandblasted texture. It is clean and free of pits, cracks, and blemishes. There is no effect to this coupon.

Stainless Steel Coupon

No change to this coupon since last month. There has been no significant pumping on the wells and no significant exposure to hazardous waste since October 2018.

COOROSION MONITORING PLAN
COUPON SUMMARY

Date	Hasteloy	Stainless Steel	Fiberglass
1/16/2020	13.326 g	10.840 g	18.033 g
2/6/2020	13.326 g	10.836 g	18.034 g

October 22, 2015

TEST REPORT


PN 125322
PO 00154

PLASTICS TESTING DEPARTMENT

Prepared For:

John Frost
Environmental Geo-Technologies, LLC
28470 Citrin Drive
Romulus, MI 48174

Prepared By: 
Melissa Martin
Sr. Project Technician

Approved By: 
Jim Drummond, Sr.
Physical & Plastic Testing, Manager



An A2LA ISO 17025 Accredited Testing Laboratory — Certificate Numbers 255.01 & 255.02
ISO 9001:2008 Registered



Letters and reports are for the exclusive use of the clients to whom they are addressed and shall not be reproduced, except in full, without the written permission of Akron Rubber Development Laboratory, Inc. (ARDL). The information contained herein applies to the specific material, products or processes tested or evaluated. No warranty of any kind is herein construed or implied. The liability of ARDL, Inc. shall be limited to the amount of consideration paid for services. ARDL, Inc. is ISO 17025 accredited by A2LA for the test methods listed on the attached scope.



October 22, 2015

John Frost
Environmental Geo-Technologies, LLC

Page 2 of 2
PN 125322

SUBJECT: Barcol Hardness on one material.

RECEIVED: One small section identified as; Fiberglass Coupon.

BARCOL HARDNESS ASTM D 2583-13a
Instant Reading

Results

Barcol Hardness, Instant

96


Prepared By:



Melissa Martin
Sr. Project Technician

to

Approved By:



Scott W. Yates
Plastics Testing Assistant Manager



Progress Through Innovation, Technology and Customer Satisfaction

December 12, 2016


-TEST REPORT-


PN 132662
PO

PLASTICS TESTING DEPARTMENT

Prepared For:

John Frost
Environmental Geo-Technologies, LLC
28470 Citrin Drive
Romulus, MI 48174

Prepared By:  _____
 Melissa Martin
 Senior Project Technician

Approved By:  _____
 Jim Drummond
 Physical Testing Manager

Rev 041916



An A2LA ISO 17025 Accredited Testing Laboratory — Certificate Numbers 255.01 & 255.02
ISO 9001:2008 Registered



Letters and reports are for the exclusive use of the clients to whom they are addressed and shall not be reproduced, except in full, without the written permission of Akron Rubber Development Laboratory, Inc. (ARDL). The information contained herein applies to the specific material, products or processes tested or evaluated. No warranty of any kind is herein construed or implied. The liability of ARDL, Inc. shall be limited to the amount of consideration paid for services. ARDL, Inc. is ISO 17025 accredited by A2LA for the test methods listed on the referenced certificates.



December 12, 2016

John Frost
Environmental Geo-Technologies, LLC

Page 2 of 2
PN 132662


SUBJECT: Barcol Hardness on one (1) material.


RECEIVED: One (1) small section identified as; Fiberglass Coupon.

BARCOL HARDNESS ASTM D 2583-13a
Instant Reading

RESULTS

Barcol Hardness, Instant 96

Prepared By: 
Melissa Martin
Senior Project Technician

Approved By: 
Scott Yates
Plastics Testing, Assistant Manager

wk

ARDL is ISO 17025 accredited by A2LA for the test methods listed on the certificates referenced on page one. ~~NOTE:~~ Non-ISO 17025 accredited test methods are designated with the ^ symbol to differentiate from ISO 17025 accredited methods in the body of the test report.



Progress Through Innovation, Technology and Customer Satisfaction

December 13, 2017

TEST REPORT

PN 139140
PO#

PLASTIC TESTING DEPARTMENT

Prepared For:

John Frost
Environmental Geo-Technologies, LLC
28470 Citrin Drive
Romulus, MI 48174

Prepared By:

Melissa Martin
Sr Project Technician

Approved By:

Jim Drummond
Rubber & Plastic Testing, Manager

Rev 041916



An A2LA ISO 17025 Accredited Testing Laboratory -- Certificate Numbers 255.01 & 255.02
ISO 9001:2008 Registered



Letters and reports are for the exclusive use of the clients to whom they are addressed and shall not be reproduced, except in full, without the written permission of Akron Rubber Development Laboratory, Inc. (ARDL). The information contained herein applies to the specific material, products or processes tested or evaluated. No warranty of any kind is herein construed or implied. The liability of ARDL, Inc. shall be limited to the amount of consideration paid for services. ARDL, Inc. is ISO 17025 accredited by A2LA for the test methods listed on the referenced certificates.

www.ardl.com | 2887 Gilchrist Rd. | Akron, Ohio 44305 | answers@ardl.com | Toll Free (800) 830-ARDL
Fax (330) 794-6610 | Worldwide (330) 794-6600



December 13, 2017

John Frost
Environmental Geo-Technologies, LLC

Page 2 of 2
PN 139140

SUBJECT: Barcol Hardness on one material.

RECEIVED: One small section identified as; Fiberglass Coupon.

BARCOL HARDNESS ASTM D 2583-13a


Instant Reading

Results

Barcol Hardness, Instant


96

Prepared By:



Melissa Martin
Sr Project Technician

Approved By:



Scott Yates
Plastics Testing, Assistant Manager

sc

ARDL is ISO 17025 accredited by A2LA for the test methods listed on the certificates referenced on page one. NOTE: Non-ISO 17025 accredited test methods are designated with the ^ symbol to differentiate from ISO 17025 accredited methods in the body of the test report.

CORROSION MONITORING COUPONS BASELINE VISUAL DESCRIPTION

November 4, 2013

Fiberglass

The fiberglass coupon is Red Box 2000 type and is 2-1/2 inches long by 1/2 inch wide and 1/4 inches thick. It is a dark orange (rust) in color with a glossy shine on one side a polished look on the opposite side and the cut edges look sanded.

Hastelloy

The hastelloy coupon is identified as C276 with serial number 1. The dimensions of the coupon are 3 inches long by 1/2 inch wide and 1/4 inch thick. The coupon is silver in color with a lightly sandblasted surface.

Stainless Steel

The stainless steel coupon is identified as 316L with serial number C1562. The dimensions of the coupon are 3 inches long by 1/2 inch wide and 1/4 inch thick. The coupon is silver in color with a lightly sandblasted surface.

GHESQUIERE PLASTIC TESTING, INC.

20450 HARPER AVENUE
HARPER WOODS, MI 48225
PHONE (313) 885-9535
FAX (313) 885-1771

Report Date: November 15, 2013
Test Date: October 15 - November 14, 2013

Report #1310-77651
Performed for:
Environmental Geo-Technologies
28470 Citrin Drive
Romulus, MI 48174

Attention: Mr. Don Anderson

WORK REQUESTED:

Perform Barcol Hardness test on sample submitted.

DESCRIPTION OF SAMPLE:

Sample submitted was identified as a fiberglass test coupon.

(P. O. #Credit Card).

WORK PERFORMED:

Test specimen was prepared as necessary and conditioned for a minimum of 24 hours at standard laboratory conditions prior to testing.

Barcol Hardness test was performed in accordance with the procedures of ASTM D2583-13. One specimen was tested.

RESULTS:


The following determination was made based upon the above test:

BARCOL HARDNESS

	<u>Hardness</u>
Specimen 1	90

Specimen is being returned with this report for further evaluation.

GHESQUIERE PLASTIC TESTING, INC.


M. W. Ghesquiere
President

MWG/kni

Our letters and reports are for the exclusive use of the client to whom they are addressed, and shall not be reproduced except in full without our written approval. Our letters and reports apply only to the sample tested and are not necessarily indicative of the qualities of apparently identical or similar products. The letters and reports and the name of Ghesquiere Plastic Testing, Inc., are not to be used under any circumstances in advertising to the general public. Samples, extra and related test materials will be destroyed 30 days after the date of the final report unless the client indicates otherwise in writing.

TOTAL 1 PAGES

GHESEQUIERE PLASTIC TESTING, INC.

20450 HARPER AVENUE
HARPER WOODS, MI 48225
PHONE (313) 885-3535
FAX (313) 885-3771

Report Date: February 17, 2014
Test Date: February 14 - 17, 2014

Report #1402-78036
Performed for:
Environmental Geo-Technologies
28470 Citrin Drive
Romulus, MI 48174

Attention: Mr. Don Anderson

WORK REQUESTED:

Perform Barcol Hardness test on sample submitted.

DESCRIPTION OF SAMPLE:

Sample submitted was identified as a fiberglass test coupon.

(P. O. #Credit Card).

WORK PERFORMED:

Test specimen was prepared as necessary and conditioned for a minimum of 24 hours at standard laboratory conditions prior to testing.

Barcol Hardness test was performed in accordance with the procedures of ASTM D2583-13. One specimen was tested.

RESULTS:

The following determination was made based upon the above test:

BARCOL HARDNESS

Hardness

Specimen 1: 90

Specimen was returned to the client on February 17, 2014.

NOTE: SEE TEST REPORT

GHESEQUIERE PLASTIC TESTING, INC.

M. W. Ghesquiere
President

MWG/dm

Our letters and reports are for the exclusive use of the client to whom they are addressed, and shall not be reproduced except in full without our written approval. Our letters and reports apply only to the sample tested and are not necessarily indicative of the qualities of apparently identical or similar products. The letters and reports and the name of Ghesquiere Plastic Testing, Inc., are not to be used under any circumstances in advertising to the general public. Samples, extra and related test materials will be destroyed 30 days after the date of the final report unless the client indicates otherwise in writing.

TOTAL 1 PAGES

Ghesquiere Plastic Testing, Inc.

20450 HARPER AVENUE
HARPER WOODS, MI 48225
PHONE (313) 885-8535
FAX (313) 885-1771

Report Date: June 16, 2014
Test Date: June 13 - 16, 2014

Report #1406-78499
Performed for:
Environmental Geo-Technologies, LLC
28470 Citrin Drive
Romulus, MI 48174

Attention: Mr. Don Anderson

WORK REQUESTED:

Perform Barcol Hardness test on sample submitted.

DESCRIPTION OF SAMPLE:

Sample submitted was identified as a fiberglass test coupon.
(P. O. #Credit Card).

WORK PERFORMED:

Test specimen was prepared as necessary and conditioned for a minimum of 24 hours at standard laboratory conditions prior to testing.

Barcol Hardness test was performed in accordance with the procedures of ASTM D2583-13. One specimen was tested.

RESULTS:

The following determination was made based upon the above test:

BARCOL HARDNESS


Hardness

Specimen 1


85

Specimen was returned to the client June 16, 2014.

Ghesquiere Plastic Testing, Inc.


M. W. Ghesquiere
President

MWG/dm



Testing. Development. Problem Solving.

October 2, 2014

TEST REPORT

PN 118325

PO Attn: John Frost

PLASTICS TESTING DEPARTMENT

Prepared For:

John Frost
Environmental Geo-Technologies, LLC
28470 Citrin Drive
Romulus, MI 48174

Prepared By:

[Signature]
Melissa Martin
Sr. Project Technician

Approved By:

[Signature]
Jim Drummond
Physical & Plastics Testing, Manager




An A2LA ISO 17025 Accredited Testing Laboratory — Certificate Numbers 255.01 & 255.02
ISO 9001:2008 Registered



Letters and reports are for the exclusive use of the clients to whom they are addressed and shall not be reproduced, except in full, without the written permission of Akron Rubber Development Laboratory, Inc. (ARDL). The information contained herein applies to the specific material, products or processes tested or evaluated. No warranty of any kind is herein constituted or implied. The liability of ARDL, Inc. shall be limited to the amount of consideration paid for services. ARDL, Inc. is ISO 17025 accredited by A2LA for the test methods listed on the attached scope.

www.ardl.com

2887 Gilchrist Rd. | Akron, Ohio 44305 | answers@ardl.com
Toll Free: (800) 830-ARDL | Worldwide: (330) 794-6600 | Fax: (330) 794-6610



Testing. Development. Problem Solving.

October 2, 2014

John Frost
Environmental Geo-Technologies, LLC

Page 2 of 2
PN118325

SUBJECT: Barcol Hardness on one material.
PO# Attn: John Frost

RECEIVED: One small section identified as; Fiberglass Coupon.


BARCOL HARDNESS ASTM D 2583-13a

Results


Barcol Hardness, Instant

97

Prepared By:


Melissa Martin
Sr. Project Technician

Approved By:


Scott W. Yates
Plastics Testing Assistant Manager

st

www.ardl.com

2887 Gilchrist Rd. | Akron, Ohio 44305 | answers@ardl.com
Toll Free (800) 830-ARDL | Worldwide (330) 794-6600 | Fax (330) 794-6610

MAINTENANCE

UIC Monthly Maintenance Log

This month the Injection well 2 workover was started. Pump house continued to be rebuilt via the pump VFD's being replaced.

INJECTION FINGERPRINTS

WASTE PROFILES